

Valvair II and SpeedKing Series: Installation / Service Instruction Sheets

Click on bulletin below to view instruction sheet in PDF format.

Document Number / Revision Level	Description	Issued Date
INSTALLATION		
V648P	<u>Time Delay Module</u>	Nov, 1998
V540P / R6	<u>A4 Single Operated Valve</u>	May, 2001
V541P / R6	<u>A4 Double Operated Valve</u>	May, 2001
V542P / R7	<u>A4 3-Position Valve</u>	May, 2001
V543P	<u>A4 Subbase and Manifold</u>	Nov, 1998
V549P / R3	<u>A4 Sandwich Regulator</u>	May, 2001
V543P	<u>A5 Subbase and Manifold</u>	Nov, 1998
V550P / R6	<u>A5 Single Operated Valve</u>	May, 2001
V551P / R6	<u>A5 Double Operated 2-Position Valve</u>	May, 2001
V552P / R6	<u>A5 3-Position Valve</u>	May, 2001
V560P / R6	<u>A6 Single Operated Valve</u>	May, 2001
V561P / R6	<u>A6 Double Operated 2-Position Valve</u>	May, 2001
V562P / R6	<u>A6 3-Position Valve</u>	May, 2001
V563P	<u>A6 Subbase and Manifold</u>	Nov, 1998
SERVICE		
V644P	<u>Solenoid Service</u>	Sept, 1999
V544P	<u>A4 Single Operated Valve</u>	Nov, 1998
V545P / R3	<u>A4 Double Operated Valve</u>	Feb, 2002
V546P	<u>A4 3-Position Valve</u>	Nov, 1998
V547P / R3	<u>A4 Sandwich Regulator</u>	Feb, 2002
V548P / R4	<u>A4 "A" Level Sandwich Regulator</u>	May, 2001
V549P / R3	<u>A4 Sandwich Regulator</u>	May, 2001
V553P / R3	<u>A5 Single Operated Valve</u>	Feb, 2002
V554P / R3	<u>A5 Double Operated 2-Position Valve</u>	Feb, 2002
V555P / R3	<u>A5 3-Position Valve</u>	Feb, 2002
V564P / R3	<u>A6 Single Operated Valve</u>	Feb, 2002
V566P	<u>A6 3-Position Valve</u>	Nov, 1998